



SKYWELL DIGITAL TECHNOLOGY INC.

| Skywell Code | OEM Code | For use with HP Printers | Page Yield | Type | REMARK |
|-------------------------|----------------------------|--|------------|-------|-----------|
| HTN505A | CE505A | HP LaserJet P2030/2035/2035n /2050 | 2300 | New | |
| HTN505X | CE505X | /2055d/2055n/2055x | 6500 | New | |
| HTN364A | CB364A | HP LaserJet 4014/4015 series/4515 | 10000 | New | |
| HTN364X | CB364X | series | 24000 | New | |
| HTN435A | CB435A | HP P1005/P1006 | 1500 | New | |
| HNN436A | CB436A | HP P1505/M1120/M1522 | 2000 | New | |
| HTN435/436 Universal | | LH435/436 UNIVERSAL | 1500 | New | |
| HTN278A | CB278A | HP 1566/1606 | 2100 | New | |
| HTN285A | CB285A | HP P1102/P1102W | 2100 | New | |
| HTN255A | 255A | LaserJet P3015, P3015d, P3015dn, | 6000 | New | |
| HTN255X | 255X | P3015x | 12500 | New | |
| HTN388A | CC388A | HP 1008/1007 | 1500 | New | |
| HTN7516A | 7516A | HP5200 | 12000 | New | |
| HTN7551A | 7551A | HP3005 | 6500 | New | |
| HTN7551X | 7551X | | 13000 | New | |
| HTN7553A | 7553A | HP2015 | 3000 | New | |
| HTN7553X | 7553X | | 7000 | New | |
| HTN5949A | Q5949A | HP1160/1320 | 2500 | New | |
| HTN5949X | Q5949X | HP1160/1320 | 6000 | New | |
| HTR5942A | Q5942A | HP 4250/4350 | 10000 | Reman | |
| HTR5942X | Q5942X | | 24000 | Reman | |
| HTN6511A | Q6511A | HP2410/2420/2430 | 6000 | New | |
| HTN6511X | Q6511X | | 12000 | New | |
| HTN7115A | C7115A | HP1000/1005/1200/1220/3300/3310/3 | 2500 | New | |
| HTN7115X | C7115X | 320/3330/3380 | 3500 | New | |
| HTN2610A | Q2610A | HP 2300 series | 6000 | New | |
| HTN2612A | Q2612A | HP1010/1012/1015/3015/3020/3030 | 2000 | New | |
| HTN2612X | Q2612X | | 3000 | New | |
| HTN2613A | Q2613A | | 2500 | New | |
| HTN2613X | Q2613X | HP 1300 | 4000 | New | |
| HTN2624A | Q2624A | HP1150 | 2500 | New | |
| HTN2624X | Q2624X | | 3500 | New | |
| HTN3906F | 3906F | HP5L/6L/3100/3150 | 2500 | New | |
| HTN4092A | C4092A | HP1100/3200 | 2500 | New | |
| HTR4096A | C4096A | HP 2000/2100/2200 | 5000 | Reman | |
| HTN4129X | C4129X | HP5000/5100 | 10000 | New | |
| Skywell Code | OEM Code | For use with CANON Printers | PAGE YIELD | Type | REMARK |
| CTNEPA | EPA | CANON LBP460/465/660/665 | 2500 | New | |
| CTN303 | CRG303/103/ 703 | CANON LBP2900 | 2000 | New | |
| CTN106 | CRG106/306 | CANON 6300/6500/6550 | 5000 | New | |
| CTNFX3 | FX-3 | CANON L200/240/250/260i/280/290 | 2500 | New | |
| CTNFX8 | FX-8/S35/ CRG W | CANON LBP2500/2700/3200 | 3500 | New | |
| CTNFX9 | FX-9/10/ CRG 104 | CANON L100/MF4150 | 2000 | New | |
| CTNEP22 | EP-22 | CANON LBP800/810/1120 | 2500 | New | |
| CTNEP25 | EP-25 | CANON LBP2500/2700/3200 | 2500 | New | |
| CTNEP26 | EP-26/27//28 CRG G/ X25 | CANON LBP2500/2700/3200 | 2500 | New | |
| CTNE30 | E-16/20/30/40 | CANON FC-210/230/310 | 2500 | New | |
| CTN308 | 308 | CANON LBP3300 | 2500 | New | |
| CTN308II | 308II | | 6000 | New | |
| Skywell Code | OEM Code | For use with SAMSUNG Printers | PAGE YIELD | Type | REMARK |
| STN3050 | ML-3050 | SAMSUNG ML3050 | 8000 | New | |
| STN1210 | ML-1210D3 | SAMSUNG ML1010/1210/1220/1250/1430 | 3000 | New | |
| STN1610 | ML-1610D2 | SAMSUNG ML1610 | 2000 | New | With Fuse |
| STN2010 | ML-2010/2571 | SAMSUNG ML 2010 | 3000 | New | With Fuse |
| STN1630 | ML-1630 | SAMSUNG ML1630 | 2000 | New | |
| STN1640 | ML-1640 | SAMSUNG ML1640 | 2000 | New | |
| STN1710 | ML-1710D3/ 1520 | SAMSUNG ML1510/1710/1750/SCX4100/4016/41 16/4216F/SF560/565/755P | 3000 | New | With Fuse |
| STN2250 | ML-2250 | SAMSUNG ML2250/2251/2252 | 5000 | New | |
| STN4100 | SCX4100 | SAMSUNG SCX4100 | 3000 | New | |
| STN4200 | SCX4200 | SAMSUNG SCX4200 | 2000 | New | |



SKYWELL DIGITAL TECHNOLOGY INC.

| STNML4500 | ML-4500D3/4600 | SAMSUNG ML4500 | 3000 | New | With Fuse |
|--------------|-----------------------------------|--|------------|------------|----------------|
| STN4520 | SCX4520 | SAMSUNG SCX4520 | 5000 | New | |
| STN4521 | SCX4521 | SAMSUNG SCX4521/4321 | 2000 | New | With Fuse |
| STN4720 | SCX4270D5 | SAMSUNG SCX4720 | 5000 | New | |
| STN4725 | SCX-D4275A/PE220(108) | SAMSUNG SCX4725 | 3000 | New | |
| STN5100 | SF-5100D3/ML-808 | SAMSUNG ML5100 | 3000 | New | |
| STN3560 | ML-3560 | SAMSUNG ML3560 | 12000 | New | |
| STN560 | SF560 | SAMSUNG SF560/560P | 3000 | New | |
| STN2150 | ML-2150D8 | SAMSUNG ML2150 | 8000 | New | |
| STNSCX4500 | SCX4500 | SAMSUNG SCX4500 | 2000 | New | |
| STNSCX4300 | SCX4300 | | 3000 | New | |
| STNSCX4600 | SCX4600 | | 1500 | New | |
| Skywell Code | OEM Code | For use with BROTHER Printers | PAGE YIELD | Type | REMARK |
| BTN8000 | TN8000/TN8050/TN200/ TN250 | BROTHER FAX8070/MFC/9030//9070/ 9160/9180 BROTHER FAX8060/9050 | 2200 | Toner Unit | No Drum |
| BTN430 | TN430/TN6300 | BROTHER HL1030/1230/1250/1430/1440/FAX4750/8350/8360/1260/1660/1650/1670/1850/1870 | 3000 | Toner Unit | No Drum |
| BTN6600 | TN460/TN6600 | BROTHER 1030/1230/1250/1430/1440/ FAX4750/8350/8360 | 6000 | Toner Unit | No Drum |
| BTN2000 | TN2000/TN350/ TN2025/ TN2050 | BROTHER HL2040/2070N/MFC7220/7420/FAX2820/DCP7010/7025 | 2500 | Toner Unit | No Drum |
| BDR2000 | DR2000/DR350/DR2025/DR2050 | BROTHER HL2040/2070N/MFC7220/7420 /FAX2820/DCP7010/7025 | 12000 | Drum Unit | No Toner Power |
| BTN3170 | TN3185/TN3170/TN3175/TN580/ TN37J | BROTHER HL5240/5250/5270 | 7000 | Toner Unit | No Drum |
| BTN2110 | TN330/TN2110/ TN2115/ TN2130 | BROTHER 330/3110/2115/2130 | 1500 | Toner Unit | No Drum |
| BTN2120 | TN360/TN2120/ TN2125/ TN2150 | BROTHER HL2140/2150/2170 | 2600 | Toner Unit | No Drum |
| BDR2100 | DR360/DR2100/DR2125/DR2150 | | 12000 | Drum Unit | |
| BTN3130 | TN550/TN3130/ TN3155/ TN3145 | BROTHER HL5240;ML5250/5250DN/5250DNT/5270DN/5280/5280DN;MFC8460N/8660DN/8860DN/8870DW | 3500 | Toner Unit | No Drum |
| BDR3100 | DR520/DR3100/DR3115/DR3150 | BROTHER HL5240/5250/5270 | 25000 | Drum Unit | |
| BTN3250 | TN620/TN3230/ TN3250 | BROTHER TN620/3230/3250 | 3500 | Toner Unit | |
| BTN3280 | TN650/TN3280/ TN3290 | BROTHER TN650/3280/3290 | 7000 | Toner Unit | |
| BDR3200 | DR620/DR3200/DR3250 | BROTHER DR620/3200/3250 | | Drum Unit | |
| Skywell Code | OEM Code | For use with LEXMARK Printers | PAGE YIELD | Type | REMARK |
| LTNE210 | E210-10S0150 | LEXMARK OPTRA E210 | 3000 | New | With Fuse |
| LTNE120 | E120 | LEXMARK E120 | 2000 | New | |
| LTNE250 | E250-UL25A21A | LEXMARK E250D/350D/352D | 3500 | New | |
| LDRE250 | E250 | | 30000 | Drum Unit | |
| LTNE450L | E450 | LEXMARK E450/450N/450DN | 6000 | New | |
| LTNE450H | E450 | | 11000 | New | |
| LTNE230L | E230 | LEXMARK E230/330 | 2500 | Toner Unit | |
| LTNE230H | E230 | | 6000 | New | |
| LTN352 | E352 | LEXMARK E350d/352d | 9000 | New | |
| Skywell Code | OEM Code | For use with XEROX Printers | PAGE YIELD | Type | REMARK |
| XTN3200 | 113R00730 | XEROX Phaser 3200 | 3000 | New | |
| XTN3110 | | XEROX 3110/3120 | 3000 | New | |
| XTN3115 | 109R00725 | XEROX 3130/3120/3115/3121 | 2500 | New | With Fuse |



SKYWELL DIGITAL TECHNOLOGY INC.

| | | | | | |
|---------------------|-----------------|--|-------------------|-------------|---------------|
| XTN3117 | 106R01159 | XEROX 3117/3122 | 3000 | New | |
| XTNPE120 | PE120 | XEROX PE120/120I | 3000 | New | |
| XTNPE220 | PE220(108) | XEROX PE220 | 3000 | New | |
| XTN3119 | | XEROX 3119 | 3000 | New | |
| Skywell Code | OEM Code | For use with PANASONIC Printers | PAGE YIELD | Type | REMARK |
| PTN76A | 76A | PANASONIC FL-501/502/503 | 2000 | Toner Unit | No Drum |
| PTN83E | 83E | PANASONIC KX-513/543/613 | 2500 | Toner Unit | No Drum |
| Skywell Code | OEM Code | For use with DELL Printers | PAGE YIELD | Type | REMARK |
| DTN1100 | | DELL 1100 | 2000 | New | |
| DTN1600 | D1600 | DELL 1600N | 5000 | New | |
| DTN1700 | | DELL 1700 | 3000 | Toner Unit | |
| DTN1720 | | DELL 1720 | 3000 | | |
| DTN1815 | D1815 | DELL 1815 | 5000 | Toner Unit | |